

**\*\*IMPORTANT NOTES - PLEASE READ!\*\***

- > All window A/C units **MUST** have **Digital Display** and **Automatic Restart**
- > Window A/C brands marked with \* have a minimum **ON** cycle time set from the factory; using an oversized A/C from these brands may lead you to experience colder than set temperatures or ice ups. Please use the recommended size A/C.
- > **A/C Secondary Sensor Guide** and **Mini-Split Installation Guide** available at: <https://storeitcold.com/support-library/>
- > For Portable A/Cs, see WHYNTER brand on page 2

**COMPATIBLE A/C UNITS****IF YOUR A/C UNIT IS NOT LISTED AS COMPATIBLE, COOLBOT CANNOT GUARANTEE ITS COMPATIBILITY****LG is our preferred brand**

BRAND	WINDOW A/C		MINI-SPLIT A/C
<b>ARCTIC KING*</b>	Any Digital Display model	12K BTU and above HAVE SECONDARY SENSOR	N/A
<b>DAIKIN</b>	N/A		<b>ONLY for 45°F and above applications</b> MINI SPLITS HAVE SECONDARY SENSORS
<b>DANBY*</b>	Any Digital Display model Avoid models pre-2011	12K BTU and above HAVE SECONDARY SENSOR	N/A
<b>FRIGIDAIRE*</b>	Any Digital Display model Avoid models pre-2015	Some 10K BTU and most above 12K BTU HAVE SECONDARY SENSOR	N/A
<b>FUJITSU</b>	N/A		<b>Any Mini Split model</b> MINI SPLITS HAVE SECONDARY SENSORS
<b>GE - GENERAL ELECTRIC</b>	Any Digital Display Model Avoid models pre-2015 Avoid AHC Models	Some 10K BTU and most above 12K BTU HAVE SECONDARY SENSOR	N/A
<b>GREE*</b>	Coolani Model <b>AUSTRALIA &amp; NZ ONLY</b>	12K BTU and above HAVE SECONDARY SENSOR	N/A
<b>GOODMAN</b>	N/A		<b>Canadian Mini Split models</b> The 24K BTU model has been tested and is a good choice. MINI SPLITS HAVE SECONDARY SENSORS
<b>HAIER</b>	Any Digital Display model Avoid HWE Models	NO SECONDARY SENSOR	N/A
<b>KELVINATOR*</b>	Any Digital Display model <b>AUSTRALIA &amp; NZ ONLY</b> Avoid CRF Models	12K BTU and above HAVE SECONDARY SENSOR	N/A
<b>LG</b>	Any Digital Display model Avoid LW6017R model	NO SECONDARY SENSOR <small>* Dual Inverter window A/Cs HAVE Secondary Sensors</small>	<b>Most Mini Splits</b> MINI SPLITS HAVE SECONDARY SENSORS <small>Models with HSV in their Model# are for 55°F+ ONLY</small>
<b>MITSUBISHI</b>	N/A		<b>Mr Slim Series is a good choice</b> MINI SPLITS HAVE SECONDARY SENSORS
<b>SAMSUNG</b>	Any Digital Display model	12K BTU and above HAVE SECONDARY SENSOR	<b>ONLY for 45°F and above applications</b> MINI SPLITS HAVE SECONDARY SENSORS

# LIMITED EXPERIENCE A/C UNITS

## Limited Experience - Limited Support A/C Units

We have some users with good results using these A/C units BUT  
we do not have enough collective data to classify them as fully compatible

We are happy to help you during installation BUT we CANNOT GUARANTEE ITS COMPATIBILITY

BRAND	WINDOW A/C		MINI-SPLIT A/C
AMANA	Limited experience - Limited support	HAS SECONDARY SENSOR	N/A
CARRIER	N/A		<b>Central And South America ONLY</b> ALL MINI SPLITS HAVE SECONDARY SENSORS
CIAC	N/A		<b>Central And South America ONLY</b> ALL MINI SPLITS HAVE SECONDARY SENSORS
COMFORT AIRE	Limited experience - Limited support	HAS SECONDARY SENSOR	<b>Central And South America ONLY</b> ALL MINI SPLITS HAVE SECONDARY SENSORS
COMFORT STAR	N/A		<b>Central And South America ONLY</b> ALL MINI SPLITS HAVE SECONDARY SENSORS
DENALI AIRE	Limited experience - Limited support	HAS SECONDARY SENSOR	N/A
FEDDERS	Limited experience - Limited support	HAS SECONDARY SENSOR	N/A
GARRISON	<b>CANADA ONLY</b>	HAS SECONDARY SENSOR	N/A
GOODMAN	N/A		<b>CANADA ONLY</b>
i-COOL	N/A		<b>Central And South America ONLY</b> ALL MINI SPLITS HAVE SECONDARY SENSORS
INNOVAIR	N/A		<b>Central And South America ONLY</b> ALL MINI SPLITS HAVE SECONDARY SENSORS
KOOL KING	Limited experience - Limited support	HAS SECONDARY SENSOR	N/A
LENNOX	N/A		<b>Central And South America ONLY</b> ALL MINI SPLITS HAVE SECONDARY SENSORS
MIDEA	N/A		Limited experience - Limited support
NOMA*	Limited experience - Limited support	HAS SECONDARY SENSOR	N/A
PERFECT AIRE*	Limited experience - Limited support	HAS SECONDARY SENSOR	N/A
PIONEER	N/A		Limited experience - Limited support MAY HAVE SECONDARY SENSORS
RHEEM/RHUUD	N/A		<b>Central And South America ONLY</b> ALL MINI SPLITS HAVE SECONDARY SENSORS
SEARS KENMORE	Limited experience - Limited support	HAS SECONDARY SENSOR	N/A
SHARP	Limited experience - Limited support	HAS SECONDARY SENSOR	Not Compatible
SOLEUS AIR	Limited experience - Limited support	HAS SECONDARY SENSOR	N/A
SPT	Limited experience - Limited support	HAS SECONDARY SENSOR	N/A
TOSHIBA	Limited experience - Limited support	HAS SECONDARY SENSOR	<b>Not Compatible- Avoid</b>
UBERHAUS	Limited experience - Limited support	HAS SECONDARY SENSOR	N/A
WESTPOINT	Limited experience - Limited support	HAS SECONDARY SENSOR	N/A
WHISPER AIR	N/A		<b>Central And South America ONLY</b> ALL MINI SPLITS HAVE SECONDARY SENSORS
WHYNTER (PORTABLE A/C)	<b>USE DUAL HOSE MODEL ONLY- HAS SECONDARY SENSOR ONLY for 54°F applications</b>		
YORK	N/A		<b>Central And South America ONLY</b> ALL MINI SPLITS HAVE SECONDARY SENSORS

# INCOMPATIBLE A/C UNITS

AVOID USING THE COOLBOT WITH THESE BRANDS

We cannot guarantee these brands will work with the CoolBot.

We suggest you try one of our supported brands.

## BRAND

AMERICAN STANDARD

BEAUMARK

BLUERIDGE

BOSCH

COOL LIVING

DAEWOO

DEGODI

DELLA

DOMETIC

ELECTROLUX

EMERSON

FRIEDRICH

GOLDSTAR

KEYSTONE

KLIMAIRE

KOLDFRONT

MAYTAG

MIDEA

MIRAGE VENTUS

MR COOL

PANASONIC

POLAR WIND

RAMSOND

RCA

SENVILLE

TAPPAN

TCL

THERMOCORE

TRANE

WESTINGHOUSE

WHIRLPOOL

**OTHER BRANDS NOT LISTED**